

### Chelmsford Street Light Project - Issue Track Log

Item	Pole No	Map Zone Designator	Street Name	St Suffix	Existing Documented Wattage	LED Retrofit Wattage	Mounting Type	Replacement Date	Label/Sticker Number	Install Crew Observations/Problems Noted
1	3	C3	John	ST	250	<b>93</b>	Cobra Head	TBD		Existing light directed toward residents shed
14	69	E6, G6, F6	RIVERNECK	RD	50	<b>25</b>	Cobra Head	12/20/2013		No Light or Arm on Pole. Head not installed.
15	12	E6, G6, F7	RIVERNECK	RD	50	<b>25</b>	Cobra Head	12/30/2013		No Light or Arm on Pole. Head not installed.
57	0003	A6	TROTTHING	RD	50	<b>25</b>	Cobra Head	3/12/2014	<b>1805</b>	Needs new wiring to Light. New head installed.
58	0009	A7	CHAMBERLAIN	RD	50	<b>25</b>	Cobra Head	3/12/2014	<b>1810</b>	Needs new wiring to Light. New head installed.
	2	B1, B2	HOPE	ST	50	<b>32</b>	Cobra Head	5/15/2014	<b>2072</b>	Needs new wiring to Light. New head installed.
71	0047	C2, D3	MIDDLESEX	ST	50	<b>26</b>	Cobra Head	4/1/2014	<b>2204</b>	Wiring to light not connected at secondary, New head installed.
72	0003	D3	HARVARD	ST	50	<b>27</b>	Cobra Head	4/1/2014	<b>2058</b>	Wiring to light not connected at secondary, New head installed.
73	0002	G6	CLANCY	ST	50	<b>28</b>	Cobra Head	4/1/2014	<b>1954</b>	Wiring to light not connected at secondary, New head installed.
77	0001	E6	GOLDEN COVE	RD	50	<b>32</b>	Cobra Head	3/27/2014	<b>2143</b>	Wiring to light not connected at secondary, New head installed.

80	0001	B8	POMFRET	RD	50	<b>32</b>	Cobra Head	3/27/2014	<b>2237</b>	Wiring to light not connected at secondary, New head installed.
82	0018	B8, C7	BYAM	RD	50	<b>32</b>	Cobra Head	3/27/2014	<b>2229</b>	Wiring to light not connected at secondary, New head installed.
85	0047	C2, D3	MIDDLESEX	ST	50	<b>32</b>	Cobra Head	4/1/2014	<b>2204</b>	Wiring to light not connected at secondary, New head installed.
86	0003	D3	HARVARD	ST	50	<b>32</b>	Cobra Head	4/1/2014	<b>2058</b>	Wiring to light not connected at secondary, New head installed.
87	0002	G6	CLANCY	ST	50	<b>32</b>	Cobra Head	4/1/2014	<b>1954</b>	Wiring to light not connected at secondary, New head installed.
88	0002	D4	RESEARCH	PL	50	<b>32</b>	Cobra Head	4/3/2014	<b>1982</b>	Wiring to light not connected at secondary, New head installed.
89			23-25 AMBLE	PL	50	<b>75</b>	Cobra Head	4/3/2014		
90			8 Essex	PL	50	<b>75</b>	Cobra Head			
91	13	E4, E5	30 STEDMAN	PL	50	<b>75</b>	Cobra Head			